




G12
3,5x25 x8



P3
x2



A5
ø7x60 x4



S2
x1



W1
x3




N13
M4x22 x2



D3
PZ35PR x2



H8
400mm x1




E38
x2




G4
4x16 x10



G2
3x20 x35



C3
Z35PR x2



A1
ø7x50 x18



B7
ø8x30 x55



W2
x1




P15
x4





G10
6x13 x4




I




II




III




IV



V



VI



VII

