



G12
3,5x25 x10



A5
ø7x60 x2



S2
x8



W1
x4




N13
M4x22 x10



D3
PZ35PR x2



H7
350mm x5



E38
x10




G4
4x16 x34




G2
3x20 x60



C3
Z35PR x2




A1
ø7x50 x11




B7
ø8x30 x76



W2
x1




P15
x5




G10
6x13 x20





I




II




III




IV



V



VI



VII

