



1. Nogi należy przykręcić do wyfrezowanego miejsca pod blatem z prawej i lewej strony. Jedną nogę należy zamocować przy pomocy 8 śrub F.

Legs should be screwed to the milled place under the top on the right and left side. Each leg must be screwed by using 8 pcs of screws „F”.



2. Do każdej wkładki należy przykręcić dwie prowadnice, każda z nich mocowana 2 śrubami „E”.

Each rail should be screwed to extension part of table top by using 2 pcs of screws „E”.



3. Wkładki należy wsunąć prowadnicami w zamontowane pod blatem 2 metalowe otwory następnie każdą wkładkę należy przykręcić do blatu stołu za pomocą 4 śrub „E”.

Each extension part should be inserted into 2 metal holes under the top table and screwed to the table top by using 4 pcs of „E” screws.

| | | |
|---|--|----|
| A | A simple rectangular board representing the main table top component. | 1 |
| B | Two U-shaped metal legs shown together. | 2 |
| C | A simple rectangular board representing the extension part of the table top. | 2 |
| D | A row of six small circular holes representing metal mounting holes. | 4 |
| E | A standard screw with a flat head and a threaded shank. | 16 |
| F | A screw with a larger, more decorative head, likely a pan head or similar. | 16 |