


G12  
3,5x25 x8



E38 x2



W1 x1




N13 M4x22 x2



D3 PZ35PR x4



H7 350mm x1



P15 x4




G4 4x16 x14




G2 3x20 x40



C3 Z350D x4




A1 ø7x50 x6



B7 ø8x30 x20



W2 x1






F1 x12




G10 6x13 x4




①



II



III



IV

