





G12

 3,5x25 x8


E38

 x3


P15

 x4


A1

 ø7x50 x22


W1


 x4


G4

 4x16 x22


B7

 ø8x30 x65


N13

 M4x22 x3

G2

 3x20 x30

W2

 x1

D3

 PZ35PR x2

C3

 Z350D x2

P3

 x2



H7

 400mm x3



G10

 6x13 x12

1




11




G10
P15
G12




III



IV



V



VI

